附件名称/Accessory Name	所有型号附件/All Models Accessory
1、充电底座。(插上电池,红灯亮起表示正在充电,绿灯亮起表示电池已充满) Charging base. (Insert the battery, the red light is on to indicate charging, and the green light is on to indicate that the battery is fully charged)	
2、电源适配器。 Power adapter.	
3、锂电池。 Lithium battery.	
4、窗口保护膜。 Window protection fi <b>l</b> m <b>.</b>	
5、校验片/窗口保护帽盖。 Calibration cap/window protection cap.	

## 操作说明 (Instructions)

1、装入电池,扣上校验片。仪器电池有防呆设计防止插反请放心插入。 Install the battery. The battery of the instrument has a fool proof design to prevent reverse insertion. Please feel free to insert it	
2、按下开机电源按钮。 Press the power button.	
3、出现开机画面。(无需任何操作,等待仪器自动启动完成开机工作) The boot screen appears.(Without any operation, wait for the automatic start of the instrument to complete the boot work)	ELASTING.
4、仪器启动并完成自校验工作。(此过程大约用时50秒) The instrument starts and completes the self-checking work. (This process takes about 50 seconds)	Analytical 加速 所能 作業化 - Passed Pale (cps) 8296 Resolution (sM) 198